


Weld Spacer to Spar Bracket

Weld Bushing to Gusset with Scrap Spacer

Landing Gear Mount Tube to be TIG Welded and then Stress Relieved to a

> Spacer Predrilled with 25/64" ( Oversize ) Holes and Edges Ground to Fit Radius



Weld Down Tube Inside Bracket 0.625" This is the CRITICAL Weld

## Maximum of 1100 degrees F

